



***TECHNICAL BULLETIN***

***[ 1 / 11 ]***

[Issue No.] GOT-A-0078-H

[Title] Production Discontinuation of GT15, GT11, GT10 Models and Some Option Units in the GOT1000 Series for Japanese Market

[Date of Issue] Ver. H: April 2017 (First Edition: August 2014)

[Relevant Models] GOT1000 Series (Models of GT15, GT11 and GT10)

---

**3. Replacement Models**

(1) Selecting the GOT

The following table shows the replacement models. For the details, refer to the following technical bulletin.

→ "Precautions when Replacing GOT1000 Series with GOT2000 Series" (GOT-A-0061)

GOT1000 Series		Recommended replacement GOT2000/GOT1000 Series	Panel cutting compatibility ○: Compatible ×: Incompatible	Applicable software GT Designer3 (GOT2000)
GT1595	GT1595-XTBA (Discontinued)	GT2715-XTBA	○ *3	Ver.1.112S or later
	GT1595-XTBD (Discontinued)	GT2715-XTBD	○ *3	Ver.1.112S or later
GT1585	GT1585V-STBA	GT2712-STBA *4	○ *3	Ver.1.100E or later
		GT2712-STWA *1*4		
	GT1585V-STBD	GT2512-STBA *5	○ *3	Ver.1.122C or later
		GT2712-STBD *4		
	GT1585-STBA	GT2712-STWD *1*4	○ *3	Ver.1.100E or later
		GT2512-STBD *5		
	GT1585-STBD	GT2712-STBA *4	○ *3	Ver.1.100E or later
		GT2712-STWA *1*4		
GT1585-STBD	GT2512-STBA *5	○ *3	Ver.1.122C or later	
	GT2712-STBD *4			
GT1585-STBD	GT2712-STWD *1*4	○ *3	Ver.1.100E or later	
	GT2512-STBD *5			
GT15	GT1575V-STBA	GT2710-STBA *4	○ *3	Ver.1.100E or later
	GT1575V-STBD	GT2710-STBD *4	○ *3	Ver.1.100E or later
	GT1575-STBA	GT2710-STBA *4	○ *3	Ver.1.100E or later
	GT1575-STBD	GT2710-STBD *4	○ *3	Ver.1.100E or later
	GT1575-VTBA	GT2710-VTBA *4	○ *3	Ver.1.100E or later
		GT2710-VTWA *1*4		
	GT1575-VTBD	GT2510-VTBA *5	○ *3	Ver.1.112S or later
		GT2510-VTWA *1*5		
	GT1575-VTBD	GT2710-VTBD *4	○ *3	Ver.1.100E or later
		GT2710-VTWD *1*4		
	GT1575-VTBD	GT2510-VTBD *5	○ *3	Ver.1.112S or later
		GT2510-VTWD *1*5		
	GT1575-VNBA	GT2710-VTBA *4	○ *3	Ver.1.100E or later
		GT2710-VTWA *1*4		
	GT1575-VNBD	GT2510-VTBA *2*5	○ *3	Ver.1.112S or later
		GT2510-VTWA *1*2*5		
GT1575-VNBD	GT2710-VTBD *4	○ *3	Ver.1.100E or later	
	GT2710-VTWD *1*4			
GT1575-VNBD	GT2510-VTBD *2*5	○ *3	Ver.1.112S or later	
	GT2510-VTWD *1*2*5			
GT1572-VNBA	GT2710-VTBA *4	○ *3	Ver.1.100E or later	
	GT2710-VTWA *1*4			
GT1572-VNBD	GT2510-VTBA *2*5	○ *3	Ver.1.112S or later	
	GT2510-VTWA *1*2*5			
GT1572-VNBD	GT2710-VTBD *4	○ *3	Ver.1.100E or later	
	GT2710-VTWD *1*4			
GT1572-VNBD	GT2510-VTBD *2*5	○ *3	Ver.1.112S or later	
	GT2510-VTWD *1*2*5			
GT156□	GT1565-VTBA	GT2708-VTBA *4	○ *3	Ver.1.100E or later
		GT2508-VTBA *5		
	GT1565-VTBD	GT2508-VTWA *1*5	○ *3	Ver.1.112S or later
		GT2708-VTBD *4		
	GT1565-VTBD	GT2508-VTBD *5	○ *3	Ver.1.100E or later
		GT2508-VTWD *1*5		
	GT1562-VNBA	GT2708-VTBA *4	○ *3	Ver.1.112S or later
		GT2508-VTBA *2*5		
GT1562-VNBD	GT2508-VTWA *1*2*5	○ *3	Ver.1.100E or later	
	GT2708-VTBD *4			
GT1562-VNBD	GT2508-VTBD *2*5	○ *3	Ver.1.112S or later	
	GT2508-VTWD *1*2*5			

GOT1000 Series		Recommended replacement GOT2000/GOT1000 Series	Panel cutting compatibility ○: Compatible ×: Incompatible	Applicable software GT Designer3 (GOT2000)		
GT15	GT155□	GT1555-VTBD	GT2705-VTBD *4*12	○ *3	Ver.1.130L or later	
		GT1555-QTBD	GT1455-QTBD□ *5*7*8	○	GT Designer3 Ver.1.37P or later	
		GT1555-QSBD	GT1455-QTBD□ *5*6*7*8	○	GT Designer3 Ver.1.37P or later	
		GT1550-QLBD	GT1450-QMBD□ *5*7*8	○	Ver.1.118Y or later	
GT11	GT115□	GT1155-QTBDA	GT1455-QTBD□ *5*6*7*18	○	GT Designer3 Ver.1.37P or later	
		GT1155-QSBDA	GT1455-QTBD□ *5*6*7*18	○	GT Designer3 Ver.1.37P or later	
		GT1150-QLBDA	GT1450-QMBD□ *5*7*18	○	Ver.1.118Y or later	
		GT1155-QTBDQ	GT1455-QTBD□ *5*6*7*9	○	GT Designer3 Ver.1.37P or later	
		GT1155-QSBDQ	GT1455-QTBD□ *5*6*7*9	○	GT Designer3 Ver.1.37P or later	
		GT1150-QLBDQ	GT1450-QMBD□ *5*7*9	○	Ver.1.118Y or later	
		GT1155-QTBD	GT1455-QTBD□ *5*6*7	○	GT Designer3 Ver.1.37P or later	
		GT1155-QSBD	GT1455-QTBD□ *5*6*7	○	GT Designer3 Ver.1.37P or later	
	GT11 Handy GOT		GT1155HS-QSBD	GT1455HS-QTBDE *5*6	○	GT Designer3 Ver.1.71Z or later
			GT1150HS-QLBD	GT1450HS-QMBDE *5	○	GT Designer3 Ver.1.71Z or later
GT105□		GT1055-QSBD	GT2105-QTBDS *5*15	○	Ver.1.144A or later	
		GT1050-QBBD	GT2105-QMBDS *5*15	○	Ver.1.144A or later	
GT104□		GT1045-QSBD	GT2104-RTBD *5*15	× *11	Ver.1.122C or later	
		GT1040-QBBD		× *11	Ver.1.122C or later	
GT10	GT1030	GT1030-HBD	GT2104-PMBDS *5*16	○	Ver.1.131M or later	
		GT1030-HBD2	GT2104-PMBDS2 *5*16	○	Ver.1.137T or later	
		GT1030-HBL	GT2104-PMBLS *5*17	○	Ver.1.137T or later	
		GT1030-HWD	GT2104-PMBDS *5*16	○	Ver.1.131M or later	
		GT1030-HWD2	GT2104-PMBDS2 *5*16	○	Ver.1.137T or later	
		GT1030-HWL	GT2104-PMBLS *5*17	○	Ver.1.137T or later	
		GT1030-HBDW	GT2104-PMBDS *5*16	○	Ver.1.131M or later	
		GT1030-HBDW2	GT2104-PMBDS2 *5*16	○	Ver.1.137T or later	
		GT1030-HBLW	GT2104-PMBLS *5*17	○	Ver.1.137T or later	
		GT1030-HWDW	GT2104-PMBDS *5*16	○	Ver.1.131M or later	
		GT1030-HWDW2	GT2104-PMBDS2 *5*16	○	Ver.1.137T or later	
		GT1030-HWLW	GT2104-PMBLS *5*17	○	Ver.1.137T or later	
GT1020		GT1020-LBD	GT2103-PMBDS *13	○	Ver.1.112S or later	
		GT1020-LBD2	GT2103-PMBDS2 *13	○	Ver.1.119Z or later	
		GT1020-LBL	GT2103-PMBLS *14	○	Ver.1.119Z or later	
		GT1020-LBDW	GT2103-PMBDS *13	○	Ver.1.112S or later	
		GT1020-LBDW2	GT2103-PMBDS2 *13	○	Ver.1.119Z or later	
		GT1020-LBLW	GT2103-PMBLS *14	○	Ver.1.119Z or later	
		GT1020-LWD	GT2103-PMBDS *13	○	Ver.1.112S or later	
		GT1020-LWD2	GT2103-PMBDS2 *13	○	Ver.1.119Z or later	
		GT1020-LWL	GT2103-PMBLS *14	○	Ver.1.119Z or later	
		GT1020-LWDW	GT2103-PMBDS *13	○	Ver.1.112S or later	
		GT1020-LWDW2	GT2103-PMBDS2 *13	○	Ver.1.119Z or later	
		GT1020-LWLW	GT2103-PMBLS *14	○	Ver.1.119Z or later	

\*1 This model has a white front panel. For the details, refer to the following technical bulletin.

→ "Precautions when Replacing GOT1000 Series with GOT2000 Series" (GOT-A-0061)

\*2 The display color specification is changed to 65536 colors since the GOT2000 series does not support the 4096-, 256-, or 16-color specification. Note that the price range differs. For the details, refer to the following catalog.

→ "Mitsubishi Graphic Operation Terminal GOT2000 Series" (L(NA)08270ENG)